



## ALEACIONES DE TUNGSTENO/WOLFRAMIO

	<b>W</b>	<b>Ni</b>	<b>Co</b>	<b>Fe</b>	<b>Ta</b>	<b>Cu</b>	<b>C</b>	<b>Otros</b>
Densalloy	96	2,00		2,00				
Carburo de tungsteno II	Balance		6,00				7	8 TIC
Carburo de tungsteno II	Balance		8,50				5	
Carburo de tungsteno III	Balance		10				5	
Otros carburos de tungsteno	Balance	5-15	10-30		8 TaC		6	